

Project: Stewart Marchman Behavioral Unit

Location: Daytona Beach, Florida

The Challenge:

Rooms were too hot or too cold, no zoning was offered with the existing system, and staff complaints of being uncomfortable. Most rooms were on interior walls where condensate pumps were used on all the fan coils.

The Solution:

Installing a Daikin Multi-Split and Single Split RA system.



“I would like to tell you how much our staff likes your product and how much it has helped with complaints about being too hot or too cold. It has been such a blessing to the facilities department with lowering the calls that we have had to go out on. We are remodeling another site within our company and I am proud to announce that we are planning on using the Daikin products in this project as well. “

Robert Kimmy, Facilities Director
Stewart Marchman Behavioral Unit

The Stewart Marchman Behavioral facility had a 7.5 ton DX split system ducted to multiple areas including a number of offices and intake rooms. Due to the nature of the business, the load was constantly shifting from one

area to another. The facilities crew were constantly called upon for service of areas either too hot or too cold. The Daikin system gives added zoning in those troublesome spots.

With the addition of the 5 fan coils in the problematic areas, staff complaints have all but disappeared and the building is more comfortable for the staff and patients.

Project information

Facilities Director: Robert Kimmy,
Stewart Marchman
Behavioral Unit

Contractor: Charles Jones, Service 1st
Port Orange, Florida

Distributor: Mark Graham
Baker Distribution
Holly Hill, Florida

Daikin AC Equipment

- 4 (Model # CTXS09GVJU) Wall Mounted Indoor Unit
- 1 (Model # FTXS18HVJU) Wall Mounted Indoor Unit
- 1 (Model # 4MXS32GVJU) Outdoor Unit
- 1 (Model # RXS18DVJU) Outdoor Unit